































Installation Standard Instructions
























ACCESSORIES LIST (SEPARATE PACKAGING)

					
No.1	G-5055-1-01-B Small door welding set *1pc	No.2	G-5055-09 Large frame welding set *1pc	No.3	G-5055-05 Lower connection welding set *2pcs
					
No.4	G-5055-07 Bracket welding set *1pc	No.5	G-5058-2007-B Locking plate *1pc	No.6	G-5000-6001 Small mounting base *4pcs
					
No.7	G-5055-02 Large shaft welding set *1pc	No.8	G-5055-11 Pulley guide welding set *1pc	No.9	50-0608 Thin weight spacer sleeve *1pc
					
No.10	G-5054-2003 Rope drum cover *1pc	No.11	G-5055-2001 Rope reel *1pc	No.12	6010-07-08 Fixed steel cable cylinder *1pc
					
No.13	G-5055-08 Steering pulley welding assembly *1pc	No.14	G-5058-08 Boom welding set *1pc	No.15	G-5058-09 Foam rod welding set *1pc
					
No.16	G-5055-1-02 Bracket welding set *1pc	No.17	G-5055-1-03 Leg press welding set *1pc	No.18	60-1002 Long counterweight head piece set *1pc


					
No.19	G-5056-2003 Guide rod *2pcs	No.20	Q1006-6012 Optical axis fixing plate *1pc	No.21	G-5055-1 Steel Wire Rope *1pc
					
No.22	G-5002-07 Handle welding set left *1pc	No.23	G-5002-06 Handle welding set right *1pc	No.24	G-5002-2002 Seat mounting plate *4pcs
					
No.25	G-5055-10 Backrest welding set *1pc	No.26	G-5058-2001 Seat cushion *1pc	No.27	G-5002-2001 Large backrest *1pc
					
No.28	G-5020-2003 Label plate *2pcs	No.29	weight stack *23pcs	No.30	41# new pull pin *1pc
					
No.31	G-5020-2002 Small door guard plate *1pc	No.32	06-MX60-0611 Counterweight rubber column *2pcs		

Blister Pack Screws List

					
A	Flat head screw M10X25 *12pcs	B	Φ10 flat washer *32pcs	C	Hexagon socket head screw (half-thread galvanized) M10X125 *8pcs
					
D	M10 lock nut *8pcs	E	Round head screw M8X20 *4pcs	F	M10*35 *3pcs
					
G	Flat head screw M10X16 *1pc	H	M8X8 set screw *2pcs	J	8X25 Ordinary flat key *1pc
					
K	8131-3002 Aluminum alloy end cap *3pcs	L	M10X25 hexagon socket countersunk screws *3pcs	M	Flat head screw M10X30 *2pcs
					
N	Flat head screw M10X20 *1pc	O	Round head screw M8X25 *4pcs	P	Φ8 flat washers *8pcs
					
Q	Round head screw M8X60 *4pcs	R	Cross recessed pan head screws M5X8 *12pcs	S	Phillips screwdriver *1pc
					
T	4mm Hexagon Wrench *1pc	U	6mm Hexagon Wrench *1pc	V	17-14 Wrench *1pc



Assembly steps

Step	Item NO	Name	Qty
1	1	G-5055-1-01-B Small door welding group	1
	2	G-5055-09 Large frame welding group	1
	3	G-5055-05 Lower connection welding group	2
	A	Flat head screw M10X25	8
	B	Φ10 flat washer	8




Assembly steps

Step	Item NO	Name	Qty
2	4	G-5055-07 Bracket welding group	1
	5	G-5058-2007-B Locking plate	1
	6	G-5000-6001 Small Mount	4
	B	Φ10 flat washer	8
	C	Hexagon socket head screw (half-thread galvanized) M10X125	4
	D	M10 Locknut	4
	E	Round head screw M8X20	4




Assembly steps

Step	Item NO	Name	Qty
3	7	G-5055-02 Large shaft welding group	1
	8	G-5055-11 Pulley guide welding group	1





Assembly steps

Step	Item NO	Name	Qty
4	9	50-0608 Thin weight spacer	1
	10	G-5054-2003 Rope reel cover	1
	11	G-5055-2001 Rope reel	1
	12	6010-07-08 Fixed cable cylinder	1
	13	G-5055-08 Steering pulley welding group	1
	B	Φ10 flat washer	4
	F	M10*35	3
	G	Flat head screw M10X16	1
	H	M8X8 set screw	2
	J	8X25 Ordinary flat key	1





Assembly steps

Step	Item NO	Name	Qty
5	14	G-5058-08 Boom welding group	1
	15	G-5058-09 Foam rod welding set	1
	K	8131-3002 Aluminum alloy end cap	2
	L	M10X25 hexagon socket countersunk screw	2





Assembly steps

Step	Item NO	Name	Qty
6	16	G-5055-1-02 Bracket welding group	1
	A	Flat head screw M10X25	4
	B	Φ10 flat washer	4




Assembly steps

Step	Item NO	Name	Qty
7	17	G-5055-1-03 Leg Press Welding Group	1
	K	8131-3002 Aluminum alloy end cap	1
	L	M10X25 hexagon socket countersunk screw	1




Assembly steps

Step	Item NO	Name	Qty
8	18	60-1002 Long counterweight head set	1
	19	G-5056-2003 Guide rod	2
	20	Q1006-6012 Optical axis fixing plate	1
	29	80KG Weight Stack	15
	30	41# New Pull Pin	1
	32	06-MX60-0611 Weighted Rubber Column	2
	M	Flat head screw M10X30	2





Assembly steps

Step	Item NO	Name	Qty
9	21	G-5055-1 Wire Rope	1





Assembly steps

Step	Item NO	Name	Qty
10	22	G-5002-07 Handle welding assembly left	1
	23	G-5002-06 Handle welding set right	1
	24	G-5002-2002 Seat mounting plate	4
	B	Φ10 flat washer	8
	C	Hexagon socket head screw (half-thread galvanized) M10X125	4
	D	M10 Locknut	4





Assembly steps

Step	Item NO	Name	Qty
11	25	G-5055-10 Backrest welding group	1
	N	Flat head screw M10X20	1



Assembly steps

Step	Item NO	Name	Qty
12	26	G-5058-2001 Seat Cushion	1
	27	G-5002-2001 Large backrest	1
	O	Round head screw M8X25	4
	P	Φ8 flat washer	8
	Q	Round head screw M8X60	4



Assembly steps

Step	Item NO	Name	Qty
13	28	G-5020-2003 Label Plate	2
	31	G-5020-2002 Small door guard	1
	R	Cross recessed pan head screw M5X8	12

